

TECHNICAL INSPECTION REPORT

Compliant with: R.D. 1215/97 & Dir. 2009/104/EC

Make GENIE	Model GTH2506	Year 2018
Serial Number GTH250618M-758	Hours 670	Stock ID #MA-881
Inspector JAVIER RUIZ MENDOZA	Date 15 / 02 / 2026	Location Sevilla, SPAIN



Scan for Full Inventory



A	B	C	S	SAFETY EQUIPMENT
☐	☐	☒	☒	1. Safety Decals
☐	☐	☒	☒	2. Operator's Manual
☐	☐	☒	☒	3. ROPs
☐	☐	☒	☒	4. Back-up Alarm
☐	☐	☒	☒	5. Seat Belts
ENGINES				
☐	☐	☒	☒	6. Belts/Tensioner
☐	☐	☒	☒	7. Exhaust Smoke
☐	☐	☒	☒	8. Unusual Noise
☐	☐	☒	☒	9. Turbocharger
☐	☐	☒	☒	10. Intake System
☐	☐	☒	☒	11. Muffler/Exhaust System
☐	☐	☒	☒	12. Fuel Pumps
☐	☐	☒	☒	13. Fuel Lines/Clamps
☐	☐	☒	☒	14. Fuel Shut-Off System
☐	☐	☒	☒	15. Fuel Throttle Linkage
☐	☐	☒	☒	16. Fuel Tank
☐	☐	☐	☐	17. _____
COOLING SYSTEM				
☐	☐	☒	☒	18. Radiator Core
☐	☐	☒	☒	19. Fan Assembly
☐	☐	☒	☒	20. Hoses/Clamps/Cap
☐	☐	☒	☒	21. Water Pump
☐	☐	☐	☐	22. _____
BRAKE SYSTEM				
☐	☐	☐	☐	23. Air Compressor
☐	☐	☐	☐	24. Bleed Air Tank
☐	☐	☐	☐	25. Linkage

A	B	C	S	BRAKE SYSTEM (CONT.)
☐	☐	☒	☒	26. Lines/Hoses
☐	☐	☒	☒	27. Parking Brake
☐	☐	☒	☒	28. Operational
STEERING SYSTEM				
☐	☐	☒	☒	29. Hoses
☐	☐	☒	☒	30. Cylinder/Valve
☐	☐	☒	☒	31. Linkage/Controls
☐	☐	☒	☒	32. Operational
FLUIDS/LUBRICATION				
☐	☐	☒	☒	33. Lubricate Grease Points
☐	☐	☒	☒	34. Engine Oil/Filter
☐	☐	☒	☒	35. Coolant
☐	☐	☒	☒	36. Hydraulic Oil
☐	☐	☒	☒	37. Transmission Oil
☐	☐	☒	☒	38. Differential Oil
☐	☐	☒	☒	39. Transmission Axle Oil
☐	☐	☒	☒	40. Front Axle Oil
☐	☐	☐	☐	41. Brake Fluid
☐	☐	☒	☒	42. Breathers
☐	☐	☐	☐	43. Planetaries
☐	☐	☐	☐	44. _____
☐	☐	☐	☐	45. _____
HYDRAULIC				
☐	☐	☒	☒	46. Lines/Hoses
☐	☐	☒	☒	47. Control/Linkage
☐	☐	☒	☒	48. Oil Cooler
☐	☐	☒	☒	49. Cylinder/Valves
☐	☐	☒	☒	50. Reservoir
☐	☐	☒	☒	51. Operational

A	B	C	S	MISCELLANEOUS
☐	☐	☐	☐	52. Bucket Teeth/Cutting Edge
☐	☐	☒	☒	53. Ground-Engaging Tools
☐	☐	☒	☒	54. Welds/Frames
☐	☐	☒	☒	55. Sheet Metal
☐	☐	☒	☒	56. Cab Mounts
☐	☐	☐	☐	57. _____
☐	☐	☐	☐	58. _____
ELECTRICAL				
☐	☐	☒	☒	59. Neutral Starting Switch
☐	☐	☒	☒	60. Connections
☐	☐	☒	☒	61. Battery Hold-Down
☐	☐	☒	☒	62. Starter
☐	☐	☒	☒	63. Alternator
☐	☐	☒	☒	64. Wipers
☐	☐	☒	☒	65. Defrost/Heat/A/C Fan
☐	☐	☒	☒	66. Turn Signals
☐	☐	☒	☒	67. Lights
☐	☐	☐	☐	68. Return-to-Dig
☐	☐	☐	☐	69. Declutch
☐	☐	☒	☒	70. All Instruments
☐	☐	☐	☐	71. _____
LEAKS				
☐	☐	☒	☒	72. Oil
☐	☐	☒	☒	73. Coolant
☐	☐	☒	☒	74. Fuel
☐	☐	☐	☐	75. Air

A	B	C	S	ADDITIONAL MAINTENANCE
☐	☐	☒	☒	76. Engine Fuel Filters
☐	☒	☐	☒	77. Engine Air Filters
☐	☐	☒	☒	78. Transmission Oil/Filters
☐	☐	☐	☐	79. Wheel Bearings
☐	☐	☒	☒	80. Hydraulic Oil/Filters
☐	☐	☒	☒	81. Fuel Injectors
☐	☒	☐	☒	82. Cab Filters
☐	☐	☒	☒	83. Engine Valve Adjustment
☐	☐	☐	☐	84. _____
☐	☐	☐	☐	85. _____
POWER TRAIN				
☐	☐	☒	☒	86. Transmission Oil Cooler
☐	☐	☒	☒	87. Driveshafts
☐	☐	☒	☒	88. Wheel Lugs
☐	☐	☒	☒	89. Tires/Pressure
☐	☐	☒	☒	90. Operational

A	CRITICAL – MUST REPAIR
B	OPERATIONAL – SIGNS OF WEAR
C	OK
S	PASSED INSPECTION - SERVICE PROVIDED